



3001 N. Darrell Rd  
Island Lake, IL 60042  
(847) 526-2166 tel • (847) 526-2241 fax

## Product Alert – Swivel Joint Repair Kits

May 13th, 2020

**Scope:** Swivel Joint Repair/Rebuild Kits sold between March 2018 and January 2020

To whom it may concern,

It has come to our attention that certain Swivel Joint Repair Kits may contain extra items, incorrect items, or be missing required components. All affected inventory has been 100% sorted for defects and containment is complete. Root Cause Corrective Actions have been implemented to prevent replication or repetition in the future. We sincerely apologize for any undo hardships or headaches this issue may have caused.

**Part #'s:** 6201SJPKC, 6215SJPKC, 6202SJPKC, 1501SJPKC, 1515SJPKC, 1502SJPKC, 1504SJPKC, 1204SJPKC

**Containment / Action:** If any Kits are found with the above stated symptoms, contact your local Kemper Sales Rep for replacement. Affected kits will have a label on the bag as shown below. Kemper will accept returns for affected kits until January 2023.

PART # : 1503SJWPKC			Kemper Heat Code 1234
DESCRIPTION: 3" FIG 1502 SWIVEL JOINT KIT CODE:RED			
<b><u>Packing Kit</u></b>	<b><u>Ball Plug Kit</u></b>	<b><u>Chrome Ball Kit</u></b>	
1x 1503SJ95W (Seal Ring)	1X 1503SJLP (Screw)	99x 3/8" Chrome Balls	
1x 1503SJ3094 (O-ring)	3X 1503SJP63 (Ball Plug)		
1x 1503SJDS (Dust Seal)	3X 1503SJR69 (Retaining Ring)		
<b>QTY:</b> 1			
<b>Notes:</b> WO# 1234 4Q17/4Q27			

Example affected kit label

Please contact your Kemper Valve Sales Rep with any questions.

Sincerely,

**Nickolas Gretz** - Product Service Engineer  
Kemper Valve and Fittings Corp., Caterpillar COGMD